



General Service Bulletin

HCOM-SB-72A

Library	Service Literature
Product Section	Refrigeration
Product	Compressor-Condensing Units
Model	Model E Hermetic
Literature Type	General Service Bulletin
Sequence	72A
Date	5/22/87
File No.	SV-RF-COM-HCOM-SB-72A-587
Supersedes	HCOM-SB-72 (5/8/87)

Literature Change: Removed erroneous "supersedes" information from literature file block.

Subject: Model "E" Compressor Terminal-Plate Retaining Ring and Cap Screw Changes

Discussion:

A design change was made to the terminal-plate retaining ring and cap screws used in the junction box assembly on all Model "E" semihermetic compressors. Original parts affected by this change are SCR-53 and RNG-132.


Corrective Action:

Whenever changeout of an original terminal-plate retaining ring (RNG-132) or cap screw (SCR-53) is necessary, be sure to replace both the ring and all 8 cap screws (Figure 1) with the redesigned components. The new part numbers for these items are RNG-962 and SCR-588.

Parts Ordering Information:

Order new terminal-plate retaining rings and cap screws from La Crosse, "Ship from 31": specify these part numbers:
SCR-588 = New Cap Screw (8 required)
RNG-962 = New Terminal-Plate Retaining Ring

Figure 1
Junction Box Assembly
(Model "E" Semihermetic
Compressors)



Terminal-Plate
 Retaining Ring
 RNG-982 (Qty. 1)

Cap Screw
 SCR-588
 (Qty. 8)

The Trane Company
 La Crosse, Wisconsin 54601-7588
 Printed in U.S.A.

© American Standard Inc. 1987

For further information on this product or other Trane products, refer to the "Trane Service Literature Catalog", ordering number IDX-JOM-1. This catalog contains listings and prices for all service literature sold by Trane. The catalog may be ordered by sending a \$20.00 check to: The Trane Company, Service Literature Sales, 3600 Pammel Creek Road, La Crosse, WI 54601.