


COMPRESSOR TERMINAL NUT TORQUE

Supersedes: Nothing

1094 Form 180.23-M2.1

TERMINAL NUT TORQUE

The torque of the nuts that attach the compressor motor lead terminal to the terminal block has been changed. The change affects the current J"F" compressor as well as the upcoming J"G" compressor. The new torque is **25 ft lbs.** See the following figure for the location of the nuts.





P.O. Box 1592, York, Pennsylvania USA 17405-1592 Copyright by York International Corporation 1994 Form 180.23-M2.1 Supersedies: Nothing



Proud Sponsor of the 1996 U.S. Olympic Team

Bubject to change without notice. Printed in USA ALL RIGHTS RESERVED SSP 2M 1094 .05 Codes: SRC

30050340